

6070 Fade-Thinner

Fade out thinner

silco[®]

- / Co more dry, patchy edges or visible repairs
- / Can be used with topcoats and clearcoats
- / Minimal or no polishing required, increasing productivity
- / Aids in achieving an invisible blend

www.silco.si



6070 Fade-Thinner

Fade out thinner

Product info

Specially formulated thinner/blender is used to dissolve the overspray and to fade out any edges created during spot repairs or blending, to make fading and blending of clearcoats and topcoats easy.

How to use?

Preparation:

1. Ensure that the panels involved are thoroughly cleaned.
2. Sand the repair area with no coarser than P800 (wet) and P400 (dry) paper.
3. Prepare the surrounding area (the area to be blended)
4. Thoroughly clean and tack the area to be refinished, ready for painting.
5. When carrying out a large blend e.g. wing into a door, it is often easier to temporarily mask off the panel to be blended.
6. Paint the repair in the usual way.
7. Remove the temporary masking, and using an arcing motion with the spraygun extend the repair into the blending area, arcing the gun away from the panel to leave a fine, dry overspray edge.

Clear coats:

1. After normal application, the gun is arced away from the panel in the blend area leaving a fine, dry overspray edge.
2. Apply 6070 Fade-Thinner to the clearcoat edge, in light coats to melt the overspray edge.
DO NOT apply heavy coats.
3. Allow the paint film to thoroughly cure.
4. If needed, lightly polish the blend area with polishing compound, taking care not to polish through the blend.

Top coats:

1. After normal application, the gun is moved away from the panel in the blend area leaving a fine, dry overspray edge
2. Apply a coat of clearcoat over the colour edge. After normal application, the gun is arced away from the panel in the blend area, leaving a fine, dry overspray edge.
3. Apply the 6070 Fade-Thinner to the clearcoat edge, in light coats to melt the overspray edge.
DO NOT apply heavy coats.
4. Allow the paint film to thoroughly cure.
5. Lightly polish the blend area with polishing compound.

Packaging

6070 Fade-Thinner, Fade out thinner

Prod. Nr.	Description	Content
6070-1	Transparent	1 L